



This is the right side of the car. The end closest to the camera is the rear of the car. The opening in the center is where the residential doorway was cut into the car side. Post 1910 there was no restroom on this side of the car. (In this view, 523 is sitting on a railway flatcar to facilitate its movement around the museum.)